ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0590, W1015, W1013, W0542, W1019, W0594, W1017, W	1st Main Rd, NA, 5th Crs, 4th Crs, 3rd Crs	Govt School
Segment No.	**Total Length (m)**	
5/C-W0590/S114936	1130.97	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	259.58	77.626226	13.097122	77.628581	13.097543	Start	End
2	60.53	77.624196	13.096824	77.624343	13.096297	Start	End
3	65.18	77.623925	13.098065	77.624088	13.097498	Start	End
4	59.25	77.624727	13.096965	77.624858	13.096445	Start.	End
5	68.59	77.624568	13.097618	77.624713	13.097015	Start	End
6	63.39	77.624037	13.097441	77.624177	13.096884	Start	End
7	201.42	77.623391	13.096644	77.625185	13.097114	Start	End
8	63.20	77.623898	13.096754	77.624051	13.096202	Satrt	End
9	61.57	77.623783	13.097344	77.623892	13.096798	Start	End
10	103.26	77.623565	13.098303	77.623769	13.097391	Start	End
11	63.55	77.623619	13.096683	77.623774	13.096129	Start	End
12	61.45	77.623506	13.097263	77.623656	13.096728	Start	End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Development and Improvements of Road, Drain and Covering Slabs at Agrahara Layout in Ward No.05	19800000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Others	RCC Drain
Tender	**Work Details**	**Job No. / Work Code**
Tender	RCC Drain, Covering Slab	005-20-000023
Work Order No.	**Work Order Date**	**Period of Extention**
EE/Project/WO/178/2019-20	10/03/2020	
Defect Liability Period From		

	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
01/10/2020	30/09/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
S K Keshavmurthy		0.00
Phone No.	**E-Mail ID**	
9902126909		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Mahanthesh Kumar
Date of Inspection	**Remarks**	
09/10/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	12/10/2020	08/11/2020	As proposed
SE	Vijay Kumar Haridas	09/10/2020	08/11/2020	Verified
EE	Devendra Naik	09/10/2020	08/11/2020	Verified

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0590, W1015, W1013, W0542,

	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
01/10/2020	30/09/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
S K Keshavmurthy		0.00
Phone No.	**E-Mail ID**	
9902126909		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Mahanthesh Kumar
Date of Inspection	**Remarks**	
09/10/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	12/10/2020	08/11/2020	As proposed
SE	Vijay Kumar Haridas	09/10/2020	08/11/2020	Verified
EE	Devendra Naik	09/10/2020	08/11/2020	Verified

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0590, W1015, W1013, W0542, W1019, W